

Date. 27th April 1987.

Page 1 of 1

SERVICE AND OPERATIONAL INFORMATION.
-----SUBJECT: Foot Throttle.

<u>MODELS AFFECTED:</u>	<u>SERIAL Nos AFFECTED</u>
PEGASUS XL-S.	ALL SERIAL No, s.
PEGASUS XL-R.	"
PEGASUS FLASH.	"
PEGASUS FLASH 2.	"

-----COMPLIANCE TIME: Immediate.
-----PURPOSE:

Field reports indicate that operators have experienced jamming of the foot throttle during the execution of hard left hand turns whilst taxiing.

-----INSTRUCTIONS:

- (i) Pre-flight checks should include the checking of the foot throttle stop and freedom of throttle travel.
 - (ii) Hard left hand turns whilst taxiing should be avoided.
-
-

MATERIAL REQUIRED: N/A
-----SPECIAL TOOLS REQUIRED: N/A
-----AVAILABILITY OF PARTS AND SPECIAL TOOLS: N/A
-----EFFECTIVITY DATE: Immediate.
-----SUMMARY:

(i) Solar Wings are investigating the incorporation of a positive steering stop into the steering system, this will be the subject of a minor modification in the near future. In the meantime follow the above instructions.

(ii) If in doubt contact your nearest dealer or phone Solar Wings Direct on:

Marlborough (0672) 54414/53598

(iii) If you are no longer in possession of the affected aircraft, please send details of change of ownership to the factory and forward this information to the current owner.