

SOLAR WINGS LTD

SERVICE BULLETIN

no. 0030

Date 26/6/91

---

SUBJECT :

Fuel Hose

MODELS AFFECTED :

All between December 1990 and July 1991

CLASSIFICATION :

Compulsory

COMPLIANCE TIME :

Immediate if perishing.

PURPOSE :

Some perishing in the outer casing of fuel hose type BSAU108 after 6 months of use has been noticed. The fuel hose should be inspected by bending it in different directions and looking for fissures. If perishing is apparent, the hose should be replaced, preferably with a different type.

Aeroquip 2556-4 hose has been tested and approved by us for use in our aircraft as a direct replacement for BSAU108. Aeroquip 2556 is available from Solar Wings, together with replacement clips, filters and taps as required.

Note: when replacing fuel hose, put a little light oil as a lubricant on to the unions. This will help to prevent internal cutting of the tube and consequent blockage. After replacement, the engine should be run at up to full power, inspecting for any leaks.

W. G. Brooks (Chief Designer).

*W.G. Brooks*