

Service Bulletin Number: 45

Issue: 1

Date: 23rd August 2001

Applicability: All Mainair Sports Two Seat Aircraft

Classification: Mandatory

Action: Install Shoulder Straps for use by the passenger, within 6 months.

Details

A recent Air Accident Investigation Bulletin has recommended that "the Civil Aviation Authority require manufacturers of UK registered microlight aircraft to provide upper body restraint to the rear seats of aircraft where forward movement of a passenger could cause injury to the pilot." This recommendation has been made mandatory by the Civil Aviation Authority.

All Mainair two seat flex wing aircraft are therefore required to be installed with shoulder straps for use by the passenger.

Owners should therefore contact Mainair Sports for shoulder straps using the form below. The cost for the straps is just £20.00 including VAT and UK post and packing (correct at time of printing).

The straps should be installed at next Permit Renewal or 6 months whichever is the soonest.

If you are no longer the owner of the aircraft referenced on the address label, please forward this bulletin onto the new owner.	

Please send 1 set of sl	houlder straps, I enclose payment/please charge my credit card for £20.00
Credit Card Details:	Card Number Expiry Date
	Issue Number/Date (Switch cards only)
Name:	
Address:	

Telephone: Home	
Aircraft Type:	Registration:

Email: flying@mainairsports.co.uk Website: www.mainairsports.co.uk