Cf. Ref. 0083

Page 1 of 2

CYCLONE AIRSPORTS Ltd ELM TREE PARK MANTON, MARLBOROUGH WILTSHIRE, SN8 1PS, UK TEL: 01672 861578

SERVICE BULLETIN no. 0083

Date 13/12/95

SUBJECT:

Three Sheave Luff Line Pulley on Q2 Wings

MODELS AFFECTED:

12 Quantum Q2 Wings. These wings will have serial numbers: 7104 to 7122.

CLASSIFICATION:

Cyclone Airsports consider this bulletin as MANDATORY

PURPOSE:

It has been noticed from a factory inspection that a batch of pulleys made by Sea Sure may be defective. The three sheave luff line pulley block concerned is located at the top of the king post. The tube which holds the pulley rings together is machined one end and peaned the other, the three sheave pulleys of this batch are not all correctly peaned. A photo of three pulleys is shown in Fig. 1., the pulleys to the left and middle of the picture show the machined end and a correctly peaned tube respectively, the pulley shown to the right has been peaned with insufficient pressure which may cause it to fail under constant use.

ACTION:

Before the next flight it is required that the owner of the Q2 wings described above should contact Cyclone Airsports Ltd at Manton, Marlborough, where a replacement pulley will be fitted on inspection. Alternatively phone or fax Cyclone Airsports Ltd to order a replacement part free of charge. Fitting instructions will be given on request. Tel: +44 (0)1672 861578 Fax: +44 (0)1672 861550.

Cf. Ref. 0083

Page 2 of 2

CYCLONE AIRSPORTS Ltd ELM TREE PARK MANTON, MARLBOROUGH WILTSHIRE, SN8 1PS, UK TEL: 01672 861578

SERVICE BULLETIN no. 0082

Date 13/12/95

SUBJECT:

Fig 1:

